



# TEST REPORT

98, Gyoyukwon-ro, Gwacheon-si, Gyeonggi-do, 13810, Korea

TEL 82-2-2164-0011

FAX 82-2-2634-1008

Report No : TAK-2020-119689

Receipt Date : 2020.08.04.

Representative : Seung-gwan, Gong

Test Completion Date : 2020.08.19.

Company name : FILTECHKOREA

Address : 8-19, Songsanpodo-ro 307beon-gil, Songsan-myeon, Hwaseong-si, Gyeonggi-do, Republic of Korea

Sample name : Vitamin Shower Filter

## Test Results

TEST ITEM	UNIT	SAMPLE	RESULT	TEST METHOD
Residual Chlorine	mg/L	After the vitamin filtering	Not Detected	The National Institute of Environment Research Notice No. 2019-63(2019.12.24)

- Usage of Report : QUALITY CONTROL

- Note :
1. The test results of this test report are only limited in to the samples and sample names provided by the client and do not guarantee the quality of all products of the client. You Can check website ([www.ktr.or.kr](http://www.ktr.or.kr)) or QR code to verify the authenticity of the certificate.
  2. This test report shall be used only within the purpose of its defined usage and shall not be used for public relation, advertisement and lawsuit.
  3. This test report is only valid when printed on KTR original report paper with hologram and when re-issued by KTR. The copy and the electronic file of the test report are only for reference.

The above testing certificate is not related to KS Q ISO/IEC 17025 and Korea Laboratory Accreditation Scheme.

*Eom sehee*

Prepared by Eom sehee

Tel : 02-2092-3831

*Kim Hongseok*

Reviewed by Kim Hongseok

Tel : 1577-0091(ARS ①→④)

2020.08.19

## Korea Testing & Research Institute

President



QR Code for forgery

Page : 1 of 1

전자문서본은 시험결과에 대한 참고용입니다.

전자문서본(Electronic Copy)